




| No | Figura | Uds. | No | Figura | Uds. | | | | |
|----|-------------|------|------------|--------|------------|---|------------|---|------------|
| 1 | | 1 | 11 | | 1 | | | | |
| 2 | | 1 | 12 | | 1 | | | | |
| 3 | | 1 | 13 | | 2 | | | | |
| 4 | | 1 | 14 | | 1 | | | | |
| 5 | | 1 | 15 | | 2 | | | | |
| 6 | | 1 | 16 | | 2 | | | | |
| 7 | | 1 | 17 | | 1 | | | | |
| 8 | | 1 | 18 | | 1 | | | | |
| 9 | | 1 | 19 | | 1 | | | | |
| 10 | | 1 | 20 | | 1 | | | | |
| A | | B | | C | | D | | E | |
| | 3,5×40 (20) | | 3,5×50 (6) | | 3,0×38 (4) | | 3,0×16 (6) | | 3,5×35 (4) |
| F | | G | | H | | | | | |
| | 3,5×25 (2) | | 3,0×22 (4) | | M3×12 (1) | | M6×45 (4) | | |




Paso 1




Paso 2




Paso 3




Paso 4




Paso 5




Paso 6




Paso 7




Paso 8




Paso 9



Paso 10



Paso 11



AVISO IMPORTANTE:

La reproducción total o parcial, así como cualquier uso comercial que se le pudiera dar a este manual, al todo o alguna de sus partes, solo mediante autorización escrita por parte de la empresa WilTec Wildanger Technik GmbH.