













No	Figure	Qty.	No	Figure	Qty.				
1		1	11		1				
2		1	12		1				
3		1	13		2				
4		1	14		1				
5		1	15		2				
6		1	16		2				
7		1	17		1				
8		1	18		1				
9		1	19		1				
10		1	20		1				
A		B		C		D		E	
	3.5×40 (20)		3.5×50 (6)		3.0×38 (4)		3.0×16 (6)		3.5×35 (4)
F		G		H					
	3.5×25 (2)		3.0×22 (4)		M3×12 (1)		M6×45 (4)		







Step 9



Step 10



Step 11



Important notice:

The reprint or reproduction, even of excerpts, and any commercial use, even in part, of this instruction manual require the written permission of WilTec Wildanger Technik GmbH.