






No	Figure	Qté	No	Figure	Qté				
1		1	11		1				
2		1	12		1				
3		1	13		2				
4		1	14		1				
5		1	15		2				
6		1	16		2				
7		1	17		1				
8		1	18		1				
9		1	19		1				
10		1	20		1				
A		B		C		D		E	
	3,5×40 (20)		3,5×50 (6)		3,0×38 (4)		3,0×16 (6)		3,5×35 (4)
F		G		H					
	3,5×25 (2)		3,0×22 (4)		M3×12 (1)		M6×45 (4)		




Étape 1




Étape 2




Étape 3




Étape 4




Étape 5






Étape 6



Étape 7



Étape 8



Avis important :

Toute reproduction et toute utilisation à des fins commerciales, même partielle de ce mode d'emploi, ne sont autorisées qu'avec l'accord préalable de la société WilTec Wildanger Technik GmbH.