





































No	Figure	Qté	No	Figure	Qté
1		1	12		2
2		1	13		1
3		1	14		2
4		1	15		1
5		1	16		1
6		1	17		1

7		1	18		1	
8		1	19			
9		10		20		1
				21		2
11			2	22		2
				23		1
				24		2

			
A 3,5×50 40	B 3,5×35 18	C 3,5×25 20	D 3,0×16 10
			
E M6×60 8	G 2	H 1	J 1







Avis important :

Toute reproduction et toute utilisation à des fins commerciales, même partielle de ce mode d'emploi, ne sont autorisées qu'avec l'accord préalable de la société WilTec Wildanger Technik GmbH.